






**MoniServ, Inc.**

<http://www.moniserv.com>

<http://www.lcdpart.com>

## Backlight Inverter Installation Procedures for Dell 1503FP





Disconnected 2backlight connectors and Connector from AD Board. Replace with good backlight inverter board. Re-install all component, metal chassis, circuit board and cover back. Dell 1701FP should work now.